

A person, entering the premises of CARMEUSE SLOVAKIA s.r.o., hereby declares that he/she has been acquainted with the applicable OSH rules, listed in enclosed newsletter.

Name, surname, company:

Date:

Signature:



Carmeuse Slovakia s.r.o., Lime plant Košice

OSH AND ENVIRONMENT PROTECTION INSTRUCTIONS FOR VISITORS



ATTENTION!!! ANY PLANT VISITOR:

Must have a clear purpose and objective of the visit.
Has to be accompanied with a responsible Carmeuse employee.
Has to observe given rules.

General rules!

Any visitor is obliged to become familiar with and observe the following rules:

1. Entry of intoxicated or drugged persons and bringing and use of alcohol and drugs in the Plant is prohibited.
2. You are obliged to wear the prescribed personal protective equipment (PPE) when moving within the Plant, except for the administrative building.
3. PPE wearing in the "green zone" (see plant map) is not obliged.
4. Entry to the operation, production and storage areas of the Plant without Carmeuse employee accompaniment is prohibited.
5. Use only the dedicated walkways for pedestrians and dedicated and safe passages, when walking.
6. Avoid any risk – if not sure, ask a Carmeuse employee for advice.
7. Smoking in closed company premises (administrative buildings, control rooms, service rooms and cabs of technological units, warehouses, workshops, switch rooms, production objects, rest rooms, sanitary facilities, etc.), except for the reserved areas identified as a "SMOKING ZONE", is prohibited.
8. In case of hazardous situation or indication thereof, you are obliged to follow instructions of Carmeuse employees.
9. Hold the handrails, when walking on stairs.
10. Staying beneath equipment (furnaces, conveyors) or within a dangerous distance from equipment in operation (mill, conveyors, sorters) is prohibited.
11. Touching of movable or rotary parts of equipment and hot surfaces is prohibited.
12. Observe the information, command, warning and prohibitive signs and labels.
13. In case of damage to health (your own or other employees), emergency situation and damage to or failure of equipment, inform the visited person immediately.

14. Perform any works with approval of visited person only.
15. Do not perform any works, you are not qualified for.
16. Do not enter or cross the rails, except for the dedicated places.

Personal protective equipment (PPE), required in Carmeuse:



Safety
hard hat



Safety
goggles



Safety
boots



Safety
clothing

In addition to above basic PPE, the additional PPE (such as earmuffs, respirator) are required at some sites and for specific activities.

Environment protection

1. Keep the Plant clean.
2. Perform works and other activities using all preventive actions, to avoid:
 - a) Escape of uncontrolled emissions to air
 - b) Leak of oils, oil and other substances that can cause water and soil contamination
3. Should a waste is generated, follow the rules for separated collection – collect waste at dedicated places only.

Important contacts

Fire alarm:
055/720 75 62

Special provisions for drivers

When driving a vehicle within the Plant, observe the highway code, road signs and speed limit of 25km/hr (3km/hr when reverse).

Stop the vehicles at the loading and unloading sites and use only the reserved parking lots for parking.

Co-driver is only allowed to enter the loading and unloading area in the vehicle cab.

Vehicle parking or staying at distance less then 3m from the track is prohibited.

Risk, presenting a threat to you

Some sites within the area of Lime plant Košice are classified as the hazardous work sites with the following risk factor:

- noise
- chemical substances (solid limestone, dolomite and lime oxide aerosols)

Due to the above reasons, you are obliged to wear the suitable personal protective means at identified workplaces.



Earmuffs



Respirator



Safety gloves

Lime is an irritant. The lime in form of dust and in mixture with water irritates eyes, air passages and skin. Direct contact with eyes can result in serious eye damage.

If you get lime in your eyes, use your personal Diphoterine kit or wash eyes with fresh water for at least 15 minutes. Never use both methods to treat the eyes, it reduces the effect of the product. After using the Diphoterine solution (or after flushing the eyes with a stream of clean water), it is necessary to visit an eye doctor.

The eye showers are present in the Lime plant Košice.

Locations of eye showers:

- control room
- administrative building ground floor

Plant map – Lime plant Košice

