

A person, entering the premises of CARMEUSE SLOVAKIA s.r.o., hereby declares that he/she has been acquainted with the applicable OSH rules, listed in enclosed newsletter.

Name, surname, company: _____

Date: _____

Signature: _____



Carmeuse Slovakia s.r.o., Lime plant Slavec

OSH AND ENVIRONMENT PROTECTION INSTRUCTIONS FOR VISITORS



ATTENTION!!!

ANY PLANT VISITOR:

Must have a clear purpose and objective of the visit.

Has to be accompanied with a responsible Carmeuse employee.

Has to observe given rules.

General rules!

Any visitor is obliged to become familiar with and observe the following rules:

1. Entry of intoxicated or drugged persons and bringing and use of alcohol and drugs in the Plant is prohibited.
2. You are obliged to wear the prescribed personal protective equipment (PPE) when moving within the Plant, except for the administrative building.
3. OOPP wearing in the "green zone"(see plant map) is not obliged.
4. Entry to the operation, production and storage areas of the Plant without Carmeuse employee accompaniment is prohibited.
5. Use only the dedicated walkways for pedestrians and dedicated and safe passages, when walking.
6. Avoid any risk – if not sure, ask a Carmeuse employee for advice.
7. Smoking in whole Carmeuse area is prohibited, except for the reserved external areas identified as a „Smoking Zone“.
8. In case of hazardous situation or indication thereof, you are obliged to follow instructions of Carmeuse employees.
9. Hold the handrails, when walking on stairs.
10. Staying beneath equipment (furnaces, conveyors) or within a dangerous distance from equipment in operation (mill, conveyors, sorters) is prohibited.
11. Touching of movable or rotary parts of equipment and hot surfaces is prohibited.
12. Observe the information, command, warning and prohibitive signs and labels.
13. In case of damage to health (your own or other employees), emergency situation and damage to or failure of equipment, inform the visited person immediately.
14. Perform any works with approval of visited person only.
15. Do not perform any works, you are not qualified for.
16. Do not enter or cross the rails, except for the dedicated places.

Personal protective equipment (PPE), required in Carmeuse:



Safety
hard hat



Safety
goggles



Safety
boots



Safety
clothing

Except for above basic PPE, the additional PPE (such as earmuffs, respirator) are required at some sites and for specific activities.

Environment protection

1. Keep the Plant clean.
2. Perform works and other activities using all preventive actions, to avoid:
 - a) Escape of uncontrolled emissions to air
 - b) Leak of oils, oil and other substances that can cause water and soil contamination
3. Should a waste is generated, follow the rules for separated collection – collect waste at dedicated places only.

Important contacts

Fire alarm:
00421 58 786 22 37